


ARC STUD WELDING ACCESSORIES

FERRULE GRIPS

**SHEAR CONNECTOR
FERRULE GRIP**


(For use with shear connector bipod foot)



STUD DIA.	GRIP DIA.	PART NO.
1/2	.680	039-174
5/8	.815	039-175
3/4	1.060	039-176
7/8	1.240	039-177

**WELD THRU DECK
FERRULE GRIP**



(For use with weld thru deck extension foot)



STUD DIA.	GRIP DIA.	PART NO.
3/4	1.060	048-399
7/8*	1.240	048-398
Mtg. Screws		016-774

*This is also used for WTD-750 Ferrule.

FERRULE TUBE & FERRULE TUBE BUSHINGS



STUD DIA.	BUSHING PART NO.	TUBE PART NO.	FOOT REQUIRED
10 GA	039-154	049-080	Small
3/16	039-155	049-081	Small
1/4	039-156	049-082	Small
5/16	039-157	049-083	Small
3/8	039-158	049-084	Small
7/16	039-159	049-085	Small
1/2	039-160	049-086	Small
5/8	039-161	049-087	Medium
3/4	039-162	039-153	Large

**NEW-AGE
FASTENING SYSTEMS, INC.**

Studwelding Equipment, Fasteners & Supplies

Boiler Outage Specialists

Jobsite Studwelding Division

P.O. Box 5658, Deptford, NJ 08096

Phone: (856) 218-8301

Fax: (856) 218-8305

Toll Free: (888) 889-3833

steve@newagestudwelding.com

All information contained herein subject to change without notice.